

NJSD New High School

MONTHLY REPORT | MARCH 2023 Miron Project Number 210210













ABOUT MIRON OUR VISION & VALUES

We recently embarked on a journey to define core values that are a more accurate reflection of Miron's culture and what we bring to every project we are honored to undertake.

Through listening sessions with employees from every facet of our organization, we gathered stories, shared experiences, and discovered commonalities, ultimately identifying values authentic to who we are today, and who we want to be for the next 100+ years.

At Miron, we Stay Grounded, Think Big, Rally Together, Dig Deep, and Build Legacies.

Our team lives out these core values every day. We put an emphasis on building lasting relationships and fulfilling the commitments we make to our clients, our partners, and each other.

As your partner throughout the construction process, we rely on transparent communication and focus on the details, standing behind our work and providing unparalleled service.



Table of Contents



Executive Summary

Action Items

Design Items

Quality

Construction Summary

Risk Management

Progress Photos

Glossary of Terms

In this issue...

Interior finishes

Auditorium equipment rigging

Locker installs

Rubber floor and carpet install

Bleachers in competition gym



Distribution List



Dr. Mary Pfeiffer District Superintendent Neenah Joint School District mpfeiffer@nenah.k12.wi.us 920-751-6800 x 10100

Tim Kippenhan Vice President & COO Miron Construction Co., Inc. Tim.Kippenhan@miron-construction.com 920-969-7053

Amanda Manteufel Project Executive Miron Construction Co., Inc. Amanda.Manteufel@miron- construction.com 920-328-1777

Matt Wolfert President Bray Architects mwolfert@brayarch.com 414-226-0200

Ryan Sands Vice President Bray Architects rsands@brayarch.com 414-290-1981

Mike Huffman President Huffman Facility Development mhuffman@huffmanfd.com 608-332-4112

Executive Summary



Overview

- · Drywall continues to be hung and finished across the building
- · Painting continues in tech labs and main building corridors
- · Ceiling grid and tile continues throughout the building
- · Casework install continues in the art and tech labs
- · Aluminum window frame glass continues to be installed throughout the building
- · Metal wall panels continues to be installed on the exterior of the building
- · MEP in-wall rough-ins, above ceiling rough-ins, and finishes continue throughout the building
- · Equipment install in the kitchen space continues
- · Carpet and rubber flooring continue
- · Lower bleachers in the competition gym started
- · Ceramic tile in the locker rooms started
- · Resinous floors continue in the locker room and kitchen spaces
- · Rigging continues in the stage portion of the auditorium
- · Musical casework continues to be installed
- · Lockers begin to be installed in various locations of the building
- · Aluminum entrance installation started at the main entrances

Major Milestones / Accomplishments

- · Lower bleacher install began in the competition gym
- · Concrete flatwork in the courtyards resumed
- · Miron quality control review started in the classroom wings

Upcoming Milestones

- · Bray/NJSD punch lists to start
- · All remaining sitework to resume

Key Issues and Concerns

- Material availability and increasing lead times
- Spring Weather



Be authentic, lead with humility, and recognize the needs of others. Care for one another and extend a helping hand wherever it's needed. Honor our history.

Action Items



Key Accomplishments

- · Building mechanical equipment start-up continues
- · Punch list phase has started

Areas of Concern

- · Material availability
- Material cost increases

Action Item List

- · Continuing to monitor material lead times and delivery dates
- · Monitoring a delivery date for electrical switchgear
- · Starting to review and collect closeout information
- · Coordination with owner furnished equipment



Learn from each experience, challenge historic thinking, continually seek a better way, and expand our capabilities.

Design Items



Areas of Concern / Focus

· Critical to continue to respond to RFI's to maintain the project schedule

Requests for Information

- 35 RFI's were generated this month and 25 have been answered and returned
- 10 open RFI's that the design team will return in early April



Get involved, respond with urgency, and work as a team to get the job done. Leverage the strengths of each individual and overcome obstacles as one.

Quality



Inspections

- Above-Ceiling Inspection
- State & Local Building Inspections

Test Results

None

Quality Issues & Resolution

• None



Bring the passion, keep moving forward, and stay focused on the results. Champion the competitive spirit, make the most of every opportunity, and stay hungry.



Labor Force Report

- Miron Concrete 3 workers
- Miron Steel 3 ironworkers
- Miron General Trades 22 carpenters
- Miron Masonry 3 masons
- Miron Door & Hardware 4 carpenters
- Appleton Lathing Corporation 22 framers and finishers
- · Appleton Lathing Corporation 4 ceiling installers
- Corcoran Paint 12 painters
- Corcoran Glass 7 workers
- Tweet Garot 5 workers
- Hurckman Mechanical 8 workers
- Blair Fire Protection 3 workers
- EC&D 4 workers
- · Van Ert 58 electricians

Miron Staff

• 8 construction management staff members on site

Delays

- Weather
 - 0 weather days in March
- Materials & Labor
 - None

Key Issues / Concerns & Recommended Action Steps

- · Continuing to track material lead times
- Tracking weather days to determine any schedule impact

- Wynn Jones 2 workers
- Muza Sheet Metal 10 workers
- Performance Firestop 2 workers
- HJ Martin 4 installers
- Resch Tile 4 installers
- Overhead Door 2 installers
- John's Refrigeration 4 installers
- · Boelter 4 installers
- Prostar Surfaces 4 installers
- Martell Construction 5 workers
- Macco's Flooring 4 installers
- · Marz & Associates 3 installers
- Gopher Stage Lighting 3 installers



Deliver unmatched quality, create meaningful connections, and craft unforgettable experiences in everything we do. Capture what truly matters and find ways to inspire.

Risk Management



Key Safety Statements & Focus Issues

While the current workforce onsite has become accustomed to the project safety expectations, it is important to ensure complacency does not settle in. The below safety topics are consistent reminders in contractor coordination meetings.

- 1577 people have been orientated to date
- Approximately 210-230 people on site per-day
- Orientations and background checks completed before being permitted to work on site
- Stretching and safety meeting is daily at 6:00 AM & 7:00 AM with all contractors
- Weekly site-wide stand-down safety meeting
- Daily site safety audits and weekly contractor safety walks
- Safety focus is hot work and lift safety
- Heavy equipment includes: 1 crane, 7 skytraks, 1 front end loader, 1 back hoe, 1 dozer, 8 UTV's, and 21 company vehicles
- Communication is key to the team's success with the amount of equipment moving on site
- Site traffic control is in place due to lots of moving equipment and vehicles on site
- Red danger tape is put up in areas where overhead work and limited access zones are located
- Elevated work permits are submitted and reviewed for each contractor working on the roof
- Air monitoring with temp heat being used across the building
- Lock out/tag out procedures in place during equipment start-up and programming
- Changing ground conditions on a daily basis with frost exiting the ground

Progress Photos





Academic lockers are installed 03/09/2023



Completed rubber flooring in the health/nurse room 03/11/2023



Completed rubber flooring 03/11/2023



Kitchen hoods are installed 03/11/2023



Kitchen equipment gets installed in the satellite serveries 03/11/2023




Casework is installed in the art rooms 03/11/2023

Progress Photos





Completed music casework 03/11/2023



Theater rigging in the auditorium has started 03/11/2023



Drywall is underway in the auditorium lobby 03/11/2023



Rubber flooring and ceiling tile installed in the main entry corridor $03\!/30\!/2023$



The main entry corridor receives paint and ceiling grid 03/11/2023



Lower bleachers are installed in the competition gym 03/30/2023



• Bid Package (BP): a set of documents that contains drawings, specifications, and scopes of work for a specific set of construction activities that are sent out to contractors for competitive bidding. Ex: Bid Package 01 contained all the drawings, specifications, and scopes for the exterior site portion of work on the project.

• Request for Information (RFI): a document during the construction phase of a project used to get clarification on the project documents between the contractor and the architect/engineer. Ex: The contractor submits an RFI to the architect about a missing dimension on the drawings.

• Submittal: documents such as shop drawings, product data, material data, and samples to confirm that the correct products will be installed on the project. Ex: The flooring contractor submits a sample of the carpet they plan to install to ensure it is the correct color.

• Compaction Report: a report generated by an engineer noting how dense the ground is in a certain location. Ex: The soil below a road is tested to ensure the soil is firm enough to handle the weight of cars driving over it.

• Concrete Masonry Unit (CMU): usually a rectangular prism shaped structural member that is cast or extruded and are comprised of designed aggregates, cement, and water. Ex: The most common occurrence of CMU units are in stairwells of a commercial building. They look like legos stacked on top of one another.

• Building Information Modeling (BIM): the process of identifying and resolving constructability issues using 3D models developed by the design team and subcontractors. 3D models are overlayed, conflicts are identified, model adjustments are made, and installation drawings are produced which allow field teams to accurately install their systems to match the final coordinated 3D model.

• Precast Concrete Wall Panel: a structural piece of concrete that is cast offsite at a production facility to specific dimensions in a mold, cured for a duration of time, and set in a final location. Precast panels can be used in lieu of a masonry wall, concrete block wall, or steel stud wall. The new high school will have precast wall panels in the auditorium and the auxiliary gym.

• Slab on Deck (SOD): a concrete slab that is poured on top of metal decking at an elevated location such as a second or third floor of a building. Together the metal deck and concrete slab make up the floor structure of the building.

 \cdot Slab on Grade (SOG): a concrete slab that is poured at the ground elevation of the building. This type of slab is poured directly on a compacted stone base.



• Topping Out: a topping out ceremony is a construction tradition that has been occurring in some fashion for centuries as a celebration of project milestones. Traditionally, this ceremony occurs when the final structural beam is raised into place, completing the building's frame.

· MEP: Mechanical, Electrical, Plumbing

• Limited Access Zone: a designated space alongside a newly constructed masonry wall restricting access in the event the wall would fail or collapse. The area is removed once the wall is complete and designed structural integrity is achieved.

• Punch List: an itemized list of minor fixes and corrections to be completed before the end of a project. Ex: A scuff on a wall needs to have the paint touched up.